Dene, PYFA filès P.



## Memorandum

To: Art Dotson, Building Development Services

From: Randy Lyman, Pretreatment Coordinator

Date: 9/9/2003

Re: Sampling & Observation Manhole-1515 E. Independence

You sent me a copy of a request by Jon Eckhardt of Malone Finkle Eckhardt & Collins seeking a variance from our sampling & observation manhole requirement for facilities like this one, a proposed Goodwrench Quick Lube to be located at 1515 E. Independence, operated by Thompson Sales, I believe. Our reason for having this requirement is to discretely monitor the wastewater discharge from facilities with wet processes other than solely domestic use that could have a potential to discharge prohibited or restricted substances. In looking at the GIS, if they were hooking into a sewer line that would never serve additional connections, we could use the first downstream city manhole as a sampling and observation manhole. But it appears that this parcel may be split and could have other connections to this sewer and we would have to go back on them at a later date and try to get a sampling manhole installed at that time. Based on these findings, a variance from this requirement is not recommended for this facility.

From the desk of...

J. Randall Lyman Pretreatment Coordinator City of Springfield, Mo. 1216 W. Nichols St. Springfield, Mo. 65802 phone 417-864-1487 fax 417-864-1918

randy\_lyman@ci.springfield.mo.us

## INDUSTRIAL PRETREATMENT PROGRAM

1216 W. Nichols St. • Springfield, Missouri 65802 417-864-1487 • fax: 417-864-1918

Post-lt* Fax Note 7671	Date 9/3/03   # ol 2
"KANDY LYMAN	From ART DOTSON
Co./Deps AN-Sues.	Co. B.D.S.
Phone #	Phone # 1074
Fax # 1918	Fax II

September 2, 2003

Mr. Art Dotson City of Springfield **Building Development Services** 840 Boonville Springfield, Mo 65802

Re: Goodwrench Quick Lube

Dear Art:

As we discussed by phone, the above project design included an oil interceptor on a waste line serving floor drains installed in a slab-on-grade floor, which will be below a raised floor of a prefabricated building. The prefabricated building floor is approximately 18" above the slab-on-grade floor. These floor drains are installed not to drain the floor above, nor to receive any specific oil wastes, but are to catch any moisture which may pass through the openings located at the vehicle lifts. The potential for oilladen waste through these floor drains is small.

I am requesting review of a detail for a method of sampling the waste downstream of the exterior oil interceptor serving these floor drains. This request is made because this method varies from the standard Department of Public Works detail for sampling manholes. We do not believe this standard sampling manhole is necessary for this installation with a small potential for oll-containing wastes.

Please consider the attached detail to be used for the purpose of sampling waste downstream of the oil interceptor.

If you have any questions or comments, please feel free to call.

Respectfully.

Malone Finkle Eckhardt & Collins, Inc.

H:\brp\tmgw\l\tmgw090203.doc

MECHANICAL ENGINEERS ELECTRICAL ENGINCERS ENERGY MANAGEMENT

2040 E. Sunshine, Springfield, Missouri 65804 🔻 eu; 417.801.0020 💿

E. Independence

Send meno to link D. re 1515 to



